KING COUL INTERNATIONAL AIRPORT INC. NT REPORT

INCIDENT:	DATE OCCURRED_11=08=91	DATE REPORTED
Fuel Spill	TIME OCCURRED 1800	TIME REPORTED
LOCATION(S) OF OCCURRENCE:		
Galvins 1		
REPORTED BY: Jim Thatcher	PHONE NO(S):	
	was spilled on the Galvin's ramp. in FD 2, applied Cejer, and washed i	t down.
OFFICERS:	LE3 — CLD CLD GO _ GO _ JE3 — JE	FILED BY

ACTION: